

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-022717**Date Inspected:** 10-Apr-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** See below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Kelly Leavitt, was present during the times noted above for random observations relative to the work being performed.

Bay 14

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Shielded Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Wong Xiang Pin, CWI Wang Jun.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

Components; OBG 14 W

PCMK: SEG3020U

Weld No: 591

Welder: 067572, 066002, 067609, 067904

WPS-B-P-2214-TC-U4b-FCM-1

Components; OBG 14 W

PCMK: SEG3020BB

Weld No: 079

Welder: 045246, 045196

WPS-B-P-2214-TC-U4b-FCM-1

WELDING INSPECTION REPORT

(Continued Page 2 of 5)

Components; OBG 14 W
PCMK: SEG3020BB
Weld No: 047
Welder: 069841, 066261
WPS-B-P-2214-TC-U4b-FCM-1

Components; OBG 14 W
PCMK: SEG3020AC
Weld No: 031
Welder: 067611
Weld Repair No. B-CWR20412
WPS-345-SMAW-2G(2F)-FCM-Repair-1

Components; OBG 14 W
PCMK: SEG3020X
Weld No: 004
Welder: 037779, 067829
WPS-B-P-2212-TC-U4b-FCM-1

Components; OBG 14 W (see photo below)
PCMK: DP3172-001
Weld No: Fit Up
Welder: 066398
WPS-B-P-2214

This QA Inspector observed the following work in progress for Bay 14.
ZPMC was using the Flux Core Arc Welding (FCAW) process.
ZPMC QC is identified as Wong Xiang Pin, CWI Wang Jun.
Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).
Listed below are the locations that were identified by this QA inspector.

Components; OBG Traveler Rails
PCMK: TR3008TR1-001
Weld No: 002,003
Welder: 066695
WPS-B-T-2232-ESAB

Components; OBG Traveler Rails
PCMK: TR3008TR3-001
Weld No: 010,011
Welder: 066734
WPS-B-T-2232-ESAB

WELDING INSPECTION REPORT

(Continued Page 3 of 5)

Components; OBG Traveler Rails

PCMK: TR3021TR2-001

Weld No: 004

Welder: 201215

WPS-B-T-2232-ESAB

Components; OBG Traveler Rails

PCMK: TR3021TR2-001

Weld No: 011

Welder: 058245

WPS-B-T-2232-ESAB

Components; OBG 14W

PCMK: SEG3020*

Weld No: 012

Welder: 045143

WPS-B-T-2232-ESAB

Components; OBG 14W

PCMK: SEG3020*

Weld No: 016

Welder: 201583

WPS-B-T-2232-ESAB

Components; OBG 14W

PCMK: SEG3020S

Weld No: 054

Welder: 062708

WPS-B-T-2233-ESAB

Components; OBG 14W

PCMK: SEG3020T

Weld No: 319,321

Welder: 048433

WPS-B-T-2232-ESAB

Components; OBG 14W

PCMK: SEG3020T

Weld No: 299

Welder: 2038713

WPS-B-T-2233-ESAB

Components; OBG 14W

PCMK: SEG3020G

WELDING INSPECTION REPORT

(Continued Page 4 of 5)

Weld No: 006
Welder: 067876
WPS-B-T-2232-ESAB

Components; OBG 14W
PCMK: SEG3020J
Weld No: 018
Welder: 066673
WPS-B-T-2233-ESAB

Components; OBG 14W
PCMK: SEG3020AH
Weld No: 014
Welder: 066614
WPS-B-T-2232-ESAB

Heat straightening of PCMK TR3002TR1-001-002,004,006,007,008,010,011, under approved Heat Straightening procedure, HSR1 (B)-10279. The in process temperature was observed as 350°C. The ZPMC QC was identified as Wong Xiang Pin. The approved HSR procedure stated that a maximum temperature of 650°C with 1-3 numbers of applications was allowed. The distortion that was previously measured and recorded on the HSR was Maximum 6mm.

Heat straightening of PCMK TR3002TR2-001-002,004,006,007,008,010,011, under approved Heat Straightening procedure, HSR1 (B)-10279. The in process temperature was observed as 390°C. The ZPMC QC was identified as Wong Xiang Pin. The approved HSR procedure stated that a maximum temperature of 650°C with 1-3 numbers of applications was allowed. The distortion that was previously measured and recorded on the HSR was Maximum 6mm.



Heat straightening of PCMK TR3008TR1-001-002,004,006,007,008,010,011, under approved Heat Straightening procedure, HSR1 (B)-10279. The in process temperature was observed as 470°C. The ZPMC QC was identified as Wong Xiang Pin. The approved HSR procedure stated that a maximum temperature of 650°C with 1-3 numbers of applications was allowed. The distortion that was previously measured and recorded on the HSR was Maximum 6mm.

Heat straightening of PCMK TR3008TR2-001-002,004,006,007,008,010,011, under approved Heat Straightening procedure, HSR1 (B)-10279. The in process temperature was observed as 420°C. The ZPMC QC was identified as Wong Xiang Pin. The approved HSR procedure stated that a maximum temperature of 650°C with 1-3 numbers of applications was allowed. The distortion that was previously measured and recorded on the HSR was Maximum 6mm.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 5 of 5)



Summary of Conversations:

“No relevant conversations.”

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact James Devey 1500026784, who represents the Office of Structural Materials for your project.

Inspected By: Leavitt,Kelly

Quality Assurance Inspector

Reviewed By: Riley,Ken

QA Reviewer